




1. 先把四个铜柱拧下来（First, unscrew the four copper standoffs.）



2. 需要按照我这个图片位置操作，使得屏幕端子露出更多，方便拆出屏幕，（You need to operate according to the position shown in the image to expose more of the screen terminals, making it easier to remove the screen.）




3.正常使用指甲扣起即可，（You can normally lift it up using your fingernail.）




4.正常使用排针焊接，注意排针长短方向不要搞反，根据自己焊接经验不要焊歪即可。（Solder the pin header

as usual. Pay attention not to reverse the long and short pin directions, and make sure not to solder crookedly based on your soldering experience.)




5. 焊接完成之后，正常用力把屏幕端子按下即可。

(After soldering is complete, simply press down the screen connector with normal force.)



6. 拧紧铜柱，固定屏幕和 PCB 即可。（Tighten the standoffs to secure the screen and the PCB.）





7.结束(END)